

### Equations, Data, Diagrams You May Find Useful

$$\log x^p = p \log x, \quad \log xy = \log x + \log y, \quad \log \frac{x}{y} = \log x - \log y$$

$$\tan \phi = \frac{r \cos \alpha}{1 - r \sin \alpha} \Rightarrow r = \frac{t_0}{t_c} = \frac{\sin \phi}{\cos(\phi - \alpha)} \quad \alpha_e = \sin^{-1}(\sin^2 i + \cos^2 i \sin \alpha_n)$$

$$r = \frac{t_0}{t_c} = \frac{V_c}{V}$$

$$\gamma = \frac{AB}{OC} = \frac{AO}{OC} + \frac{OB}{OC} \Rightarrow \gamma = \cot \phi + \tan(\phi - \alpha)$$

$$\text{Shear Stress} = \frac{F_s}{\text{Area of the shear plane}}$$

$$\phi = 45^\circ + \frac{\alpha}{2} - \frac{\beta}{2} \quad (\text{when } \mu = 0.5 \sim 2)$$

$$\Rightarrow \phi = 45^\circ + \alpha - \beta$$

$$\frac{V}{\cos(\phi - \alpha)} = \frac{V_s}{\cos \alpha} = \frac{V_c}{\sin \phi}$$

$$VT^n d^x f^y = C$$

$$T = C^{1/n} V^{-1/n} d^{-x/n} f^{-y/n}$$

$$T \approx C^7 V^{-7} d^{-1} f^{-4}$$

$$\sigma_s = \frac{F_n \sin \phi}{t_0 W} \quad \sigma = \frac{N}{t_c W}$$

$$\text{Power} = F_c V$$

$$\text{Power for friction} = F V_c$$

$$\text{Power for shearing} = F_s V_s$$

$$R_t = \frac{f^2}{8R}$$

$$\tau_s = \frac{F_s \sin \phi}{t_0 W} \quad \tau = \frac{F}{t_c W}$$

$$u_t = u_s + u_f \quad u_s = \frac{F_s V_s}{w t_0 V}$$

$$u_f = \frac{F V_c}{w t_0 V} = \frac{F r}{w t_0}$$

$$\eta_{mech} = \frac{\text{Power}_c}{\text{Power}_{source}}$$


$$\mu = \tan \beta = \frac{F}{N} = \frac{F_t + F_c \tan \alpha}{F_c - F_t \tan \alpha}$$

$$F_s = F_c \cos \phi - F_t \sin \phi$$

$$F_n = F_c \sin \phi + F_t \cos \phi$$

#### Ranges of n Values for the Taylor Equation (21.20a) for Various Tool Materials



High-speed steels	0.08–0.2
Cast alloys	0.1–0.15
Carbides	0.2–0.5
Coated carbides	0.4–0.6
Ceramics	0.5–0.7



□ Recommended cutting speed is one producing tool life:

- 60-120 min: high-speed steel tools
- 30-60 min: carbide tools

$$F_t = R \sin(\beta - \alpha) \quad \text{or} \quad F_t = F_c \tan(\beta - \alpha)$$



#### Approximate Range of Energy Requirements in Cutting Operations at the Drive Motor of the Machine Tool (for Dull Tools, Multiply by 1.25)

Material	Specific energy W · s/mm <sup>3</sup>
Aluminum alloys	0.4–1
Cast irons	1.1–5.4
Copper alloys	1.4–3.2
High-temperature alloys	3.2–8
Magnesium alloys	0.3–0.6
Nickel alloys	4.8–6.7
Refractory alloys	3–9
Stainless steels	2–5
Steels	2–9
Titanium alloys	2–5